

## BONITO PRO FIRMWARE RELEASE NOTES

## Bonito PRO cameras

2018-May-31

**Firmware update instructions**

For information on updating the firmware on your Bonito PRO camera, see the *Bonito PRO Technical Manual* at <https://www.alliedvision.com/en/support/technical-documentation.html>.

**Camera feature reference**

For information on the Bonito PRO camera features, see the *Bonito PRO Features Reference* at <https://www.alliedvision.com/en/support/technical-documentation.html>.

Firmware version: 00.01.00.20247 (release date: 2018-May-31)

**Supported models**

Camera family	Model
Bonito PRO	X-1250B, X-1250B NIR, X-1250C, X-2620B, X-2620B NIR, X-2620C

**New models**

Initial commercial release of Bonito PRO X-1250B, X-1250B NIR, X-1250C, X-2620B, X-2620B NIR, X-2620C

**Known issues**

Issue ID	Description
CXP-92	Matrox frame grabber displays a <i>Synchronization Lost</i> error and does not stream. Workaround: Use the Euresys, Active Silicon, Teledyne DALSA, Silicon Software, or Bitflow frame grabber.

## Additional References

For technical support, please contact [support@alliedvision.com](mailto:support@alliedvision.com).

For comments or suggestions regarding this document, please contact [info@alliedvision.com](mailto:info@alliedvision.com)

## Disclaimer

For the latest version of this document, please visit the [Allied Vision documentation website](#).

All trademarks are acknowledged as property of their respective owners.

Copyright © 2018 Allied Vision Technologies GmbH. All rights reserved.