

Affected Product Mako camera series (monochrome sensor models)
PCN Title Removed cover ring in Mako monochrome models
PCN No. 2014-03-02 **PCN Issue date** 2014-July-18
Contact pcn@alliedvisiontec.com

Type of change

- | | |
|--|--|
| <input type="checkbox"/> Regulatory / Compliance | <input type="checkbox"/> Firmware Specification |
| <input checked="" type="checkbox"/> Mechanical Specification | <input type="checkbox"/> Accessories Specification |
| <input type="checkbox"/> Electrical Specification | <input type="checkbox"/> DISC (Discontinued) |
| <input type="checkbox"/> Optical Specification | <input type="checkbox"/> |

Affected item number(s)


5051, 5046, 5052, 5490, 6408, 5082, 5048, 5049, 5084, 5487, 5086, 5044, 6410, 5080

Reason for change

Change of manufacturing process

Change description

To date, all monochrome Mako models are equipped with a cover ring in the lens-mount.
 The above mentioned Mako camera models item ids with serial number 536873083 and higher will be shipped without the cover ring in the C-Mount thread.
 The removal of the ring has no influence on camera properties, parameters or image performance.



Last time buy date

n/a

Last time ship date

n/a

Customer action request

No action required.

Possible successor

n/a